

#### engineering and constructing a better tomorrow

June 10, 2011

Mr. Christopher O'Neill, P.E. New York State Department of Environmental Conservation Office of Environmental Quality, Region 4 1130 North Westcott Road Schenectady, New York 12306-2014

Subject: Vapor Intrusion Investigation Report

Spill #99909741 Former Furon Site 1 Liberty Street

Hoosick Falls, New York

Dear Mr. O'Neill,

Mactec Engineering and Consulting, Inc. (Mactec) has prepared this Vapor Intrusion Investigation Report (VI Report) on behalf of our client, Honeywell International Inc. (Honeywell), to document the results of vapor intrusion sampling completed in January 2011 at the referenced location. The work was completed as outlined in the Additional Vapor Intrusion Work Plan dated November 2, 2010, and as described below.

#### SITE DESCRIPTION

Allied Signal (a Honeywell predecessor) sold the referenced facility to Furon Company in February 1996. Saint-Gobain Corporation (Saint-Gobain) acquired the facility from Furon in December 1999. Saint-Gobain currently owns and operates the manufacturing facility.

The Liberty Street site (Site) is an active plastics manufacturing facility which consists of a rectangular series of interconnected buildings located in the approximate center of the property. Paved and gravel covered parking areas and driveways surround the buildings. There are several small courtyard areas located between the buildings. Grass-covered areas are located around the perimeter of the property. Saint-Gobain reports that the buildings are slab-on-grade with no basements.

#### SUMMARY OF PREVIOUS INVESTIGATIONS AND REMEDIATION ACTIVITIES

A Phase II Environmental Site Assessment (ESA) was completed for the Liberty Street facility in 1996 by Parsons Engineering Science, Inc. (Parsons). The results of the Phase II ESA were documented in a

**MACTEC Engineering and Consulting, Inc.** 

800 North Bell Avenue, Suite 200 • Pittsburgh, PA 15106 • Phone: 412-279-6661 • Fax: 412-279-8567

www.mactec.com

June 2011

Parsons report dated May 1996. Among the findings of note, a soil sample collected in a small courtyard on the eastern side of the facility contained concentrations of chlorinated volatile organic compounds (VOCs) that exceeded the New York State Department of Environmental Conservation (NYSDEC) Technical and Administrative Guidance Memorandum (TAGM) 4046 guidance values. Parsons recommended further evaluation of the area.

In late 1999, a Honeywell contractor completed remedial activities for the courtyard area that involved the excavation and off-site disposal of soils impacted by trichloroethene (TCE) and breakdown products. A letter report dated March 8, 2000 was issued by Parsons that documented the work and provided conclusions and recommendations. During the excavation work, a sheen was noted on water that had accumulated within the excavation and a spill notification was subsequently made to NYSDEC (Spill No. 99-09741). The final excavation dimensions were reported to be 7 feet wide, 16 feet long and 10 feet deep. Side wall samples collected from the excavation did not exceed TAGM 4046 soil cleanup objectives. A sample collected from the bottom of the excavation contained reported concentrations of TCE (1,800 ug/kg) and cis-1,2-dichloroethene (DCE) (810 ug/kg) that exceeded the TAGM guidance values of 700 ug/kg and 300 ug/kg, respectively. In addition, tetrachloroethene (PCE) was not detected in the soil sample collected within the facility courtyard (the detection limit for PCE was 3.4 μg/Kg).

Due to access limitations associated with the courtyard location and adjacent facility buildings; it was not possible to deepen the excavation. However, because clay soils were encountered at the bottom of the excavation and because the adjacent buildings do not have basements, Parsons concluded that only a small amount of impacted soil remained and that no vapor intrusion hazard was present. The excavation was therefore backfilled to grade with flowable cement to complete the remedial activities.

It should be noted that the current restricted use Soil Cleanup Objectives (SCOs) at industrial sites, as established under 6 NYCRR Part 375, are 400,000 ug/kg for TCE and 1,000,000 ug/kg for cis-1,2-dichloroethene. Thus, the concentrations of TCE and cis-1,2-DCE reported in soil at the Liberty Street courtyard remediation area in 1999 are orders of magnitude lower than the SCO criteria for direct contact risk. However, the prior investigations did not quantitatively evaluate the potential risk from vapor intrusion.

In a response to the 2006 letter issued to Saint-Gobain from the NYSDEC requesting the evaluation of vapor intrusion (VI) potential at the former Furon facility, Mactec investigated conditions at the Site. In 2009, NYSDEC issued a letter directing that VI investigation work was required for the Liberty Street

facility in order to evaluate the VI pathway in accordance NY state guidance. Mactec, on behalf of

Honeywell, issued an SVI sampling plan dated November 4, 2009 that was reviewed and approved by

NYSDEC. VI sampling was conducted at the facility on January 20, 2010 (during the 2009/2010 winter

heating season).

The results of the January 2010 VI sampling event were presented to NYSDEC in a Mactec letter report

dated June 30, 2010. Several VOCs were detected in sub-slab soil vapor and indoor air samples. Based

on the product inventory and interviews with Site personnel, as well as comparison of sub-slab vapor

concentrations to indoor air concentrations, it was concluded by Mactec that most of the VOCs detected

within the facility indoor air samples were likely attributed to stored or current material usage and

manufacturing processes or other sources (such as items associated with contractors or employees).

However, TCE, the primary contaminant of concern with respect to the VI sample analytical results, was

detected in sub-slab vapor at a concentration of 540 µg/m<sup>3</sup>. TCE was detected in the indoor air at a

concentration of 5.9 µg/m<sup>3</sup>, which exceeds the NYSDOH indoor air guidance value for TCE (based on a

residential exposure scenario) of 5 µg/m<sup>3</sup>. By comparison, the EPA Regional Screening Level (RSL),

which is a guidance value set at 10-6 risk and hazard index of 1, is 6.2 ug/m<sup>3</sup> for industrial facilities.

Based on the results of the January 2010 VI investigation, NYSDEC issued a letter to Mactec dated

September 15, 2010, that requested mitigation "in order to eliminate potential exposures to TCE in the

indoor air" and that "indoor air monitoring be conducted to evaluate current exposures". The NYSDEC

letter stated that additional information regarding building construction, specifically information

regarding footers and drains, should be obtained. In response to the NYSDEC comments, Mactec

prepared an Additional Vapor Intrusion Work Plan, dated November 2, 2010. This report documents the

results of implementation of the November 2010 Work Plan.

**SCOPE OF WORK** 

The following sections describe the scope of work associated with the January 2011 VI sampling event

completed at the Liberty Street facility.

**Site Inspection** 

Mactec visited the Liberty Street site on January 25, 2011 and met with Saint-Gobain representative Mr.

PJ Beaumont (Maintenance and Facility Engineering Manager) to gather additional information regarding

3

site conditions, building subsurface utilities, and further evaluate the facility floor drain system. Also in attendance were Mr. Chris O'Neill (NYSDEC) and Mr. Albert DeMarco (NYSDOH). During the site inspection, proposed locations for permanent sub-slab sampling points and indoor air samples were identified and reviewed with NYSDEC and NYSDOH personnel for approval. Sample locations focused on areas with the greatest potential for VI exposure based on available information.

During the site inspection, Mactec completed a brief indoor chemical inspection of the building. Based on discussions with the NYSDOH and NYSDEC, it was determined that the full chemical inventory and photoionization detector (PID) survey would be conducted at the time of sampling. In addition, the NYSDEC and the NYSDOH representatives stated that the chemical inventory should be conducted in each room where the samples were being collected (i.e. kitchen and office), and in the immediate vicinity of the rooms to be sampled, but the inspection did not need to include the entire facility due to the facility size and the confined areas to be sampled. Chemical inventory information is provided on the Indoor Air Quality and Building Inventory form provided in Attachment A. Mactec also further interviewed Saint-Gobain representatives to collect information regarding past and present chemical usage at the facility. Although Saint-Gobain representatives have historically stated that toluene, xylene, and ethylbenzene were used in the facility, the primary chemicals used in the plastics manufacturing process at the facility were proprietary and could not be revealed.

Due to the openness of the facilities and the apparent large air exchange rate with exterior air in the main buildings, the primary potential health risk is anticipated to be in the smaller occupied areas. Based on this information and data collected by Mactec in 2010, as well as discussions with the NYSDEC and NYSDOH during the site inspection, it was determined that six permanent sub-slab sample points would be installed for collection of subslab vapor samples and six indoor air samples would be collected, as well as one outdoor ambient air sample. This was consistent with the November 2010 Work Plan. The sub-slab sample locations were chosen after review of the facility during the site inspection and were based on proximity to potential contamination areas, as well as layout (i.e. footings and floor drains) and floor construction of the buildings. The locations of the January 2011 VI samples are shown on Figure 1.

#### **Vapor Intrusion Sampling (January 2011)**

VI sampling was conducted at the Liberty Street facility on January 26, 2011 (during the 2010/2011 winter heating season). The facility is an active manufacturing facility and samples were collected during regular working hours.

June 2011

MACTEC Project: 3410100802

The additional VI sampling was conducted in general accordance with the November 2, 2010 Work Plan. The sampling methods comply with current NYSDOH VI guidance. The previous three sub-slab sample locations were re-sampled in 2011, along with three new locations. In general, the SVI sampling steps were:

- 1. Survey the sampling locations with a PID and complete an Indoor Air Quality Questionnaire and Building Inventory Form (completed Field Data Records are included in Attachment A). PID readings within the facility are also shown on Figure 1. PID readings within the facility ranged from 750 parts per billion (ppb) to 5,500 ppb.
- 2. Drill a 1.25-inch hole through the buildings' slab at each of the six sub-slab locations (electrical room, warehouse, supervisor's office, Quality Assurance [QA] office, human resources office, and hallway) approximately two-inches into the concrete. The 1.25-inch hole was then advanced approximately 1 to 2 inches through the slab with a 5/8-inch drill bit.
- 3. A 7-inch stainless-steel Swagelok permanent sub-slab soil vapor sampling point was then installed in the hole. The vapor points were completed at the ground surface with a fast drying hydraulic cement. A diagram of the permanent soil vapor point installation is included in Attachment B.
- 4. Approximately 12 hours after installing the permanent soil vapor points, one 60 cc volume was purged with a Syringe from the points prior to connecting the SUMMA canisters. The sub-slab samples were then connected to the soil vapor point with ¼-inch solid Teflon tubing using a stainless steel nut, feral and collar.
- 5. Set up six indoor air SUMMA canisters (breakroom, breakroom adjacent to maintenance shop supervisor's office, QA office, human resources office, and hallway) and one outdoor ambient air SUMMA canister (set in open courtyard).
- 6. Open valves on all canisters at roughly the same time for 8-hour sample collection time.
- 7. Check the sample flow valves periodically during the 8-hour time frame to ensure that the samples were being collected over the proper time interval.
- 8. After the 8-hour sampling period had elapsed, pick up the canisters and place stainless-steel caps back on the permanent soil vapor points.
- Label and ship the SUMMA canister samples with chain-of-custody to Test America, a NYSDOH ELAP certified laboratory. Samples were analyzed for VOCs by USEPA TO-15 analysis.

#### **Data Evaluation**

Upon receipt of the laboratory analysis, a data usability summary report (DUSR) was completed by a Mactec chemist following the NYSDEC guidance (NYSDEC, 2002). Based on the outcome of the DUSR, the data was deemed usable as presented in this report. The DUSR and complete analytical data is included in Attachment C. Detected compounds and analytical results for the Liberty Street Site are summarized in Table 1.

MACTEC Project: 3410100802

Several VOCs were detected in the soil vapor and indoor air samples collected at the Liberty Street facility in January 2011. Based on the product inventory and interviews with Site personnel, as well as a comparison of sub-slab vapor concentrations to indoor air concentrations, most of the VOCs detected within the facility are likely to be related to manufacturing processes within the building. These include the compounds that facility personnel indicated were used within the facility (toluene, ethylbenzene, and xylene).

Several aerosol canisters of Zep Lubrisil, both used and unused, were observed by Mactec in the machine shop during the chemical inventory in January 2011. The can labels identified TCE and PCE as the main constituents in Zep Lubrisil, a silicone lubricant and mold releasing agent. Photographs taken during the January 2011 VI sampling event are included in Attachment D. PCE concentrations detected in the indoor air adjacent to the machine shop  $(2,200 \ \mu g/M^3 \ at \ IA-02)$  were an order of magnitude greater than the adjacent sub-slab soil vapor sample  $(160 \ \mu g/M^3 \ at \ SS-05)$ , indicating that the PCE detections in the facility are likely the result of the use of the chemical within the facility.

TCE is the primary chemical of concern for soil vapor intrusion from the historic soil removal within the facility courtyard. The highest concentrations of TCE detected in sub-slab vapor were from samples SS-1 (1,100  $\mu$ g/M³) and SS-7 (560  $\mu$ g/M³). The highest TCE concentration detected in indoor air was 45  $\mu$ g/M³. Although the indoor air detection may be influenced by soil vapor intrusion, it is likely primarily the result of chemicals used/stored within the facility, or the breakdown product of the PCE detected in the indoor air within the facility. Although the NYSDOH indoor air guidance value for TCE is 5  $\mu$ g/M³, this guidance value is protective for residential exposures.

In addition, due to the use of PCE and TCE within the facility (in the Zep Lubrisil), Occupational Safety and Health Administration (OSHA) Permissible Exposure Limits (PEL) are used for industrial settings. These limits are  $685,000 \,\mu\text{g/M}^3$  for PCE and  $537,000 \,\mu\text{g/M}^3$  for TCE. American Conference of Industrial Hygienists threshold limit values (TLVs) are often considered more conservative for industrial corporations and therefore more applicable than the PEL limits. The TLV for PCE is  $170,000 \,\mu\text{g/M}^3$  and for TCE is  $54,000 \,\mu\text{g/M}^3$ . Based on these values, and the use of PCE and TCE within the facility, vapor intrusion is does not appear to be resulting in an increased health risk for workers within the facility. Therefore no further investigation of the SVI pathway is recommended.

MACTEC Project: 3410100802

We trust that this VI Report satisfies the requirements of NYSDEC. Please contact Mr. Richard Galloway of Honeywell at (973) 455-4640 or Mr. John Scrabis of Mactec at (412) 279-6661 should you have any questions or require additional information.

Sincerely,

Mactec Engineering and Consulting, Inc.

Brandon Shaw Project Scientist

Sr. Principal Engineer

- how (for JMS with permission)


CS:JMS/llg

w/atts

cc: S.Coladonato (Honeywell)

J. Smith (Saint-Gobain)

P:\Projects\Honeywell\Hoosick Falls\4.0 Project Deliverables\4.1 Reports\2011 VI Reports\Liberty Street VI Report\Final\Liberty Street-2011 VI Report June2011.docx



HONEPAHOOSICK-0000399

Table 1: 2011 Soil Vapor/Indoor Air VOC Results

Location Sample ID Sample Date	LS-AA-01-2 AA-01-2 01/26/11	LS-IA-01-2 IA-01-2 01/26/11	LS-IA-02-2 IA-02-2 01/26/11	LS-IA-03-2 IA-03-2 01/26/11	LS-IA-04-2 IA-04-2 01/26/11
Parameter Name	Result Qualifier				
1,1,1-TRICHLOROETHANE	0.27 U	1.1 U	5.5 U	2.7 U	11 U
1,2-DICHLOROETHANE	0.061 U	0. <b>24</b> U	1.2 U	0.61 U	2.5 U
1,2-DICHLOROETHENE (TOTAL)	0.4 U	1.6 U	7.9 U	4 U	16 U
1,2-DICHLOROTETRAFLUOROETHANE	0.084 U	0.34 U	<b>11</b> J	0.84 U	3.4 U
1,3,5-TRIMETHYLBENZENE	0.31 U	1.3 U	6.3 U	3.1 U	13 U
2,2,4-TRIMETHYLPENTANE	0.061 U	0. <b>24</b> U	1.2 U	0.61 U	2.5 U
4-ETHYLTOLUENE	0.31 U	1.3 U	6.3 U	3.1 U	13 U
BENZENE	1.1	2.7	<b>4.6</b> J	<b>4.9</b> J	<b>6.9</b> J
BROMODICHLOROMETHANE	0.34 U	1.3 U	6.7 U	3.4 U	14 U
CARBON TETRACHLORIDE	<b>0.5</b> J	1.3 U	6.3 U	3.1 U	13 U
CHLOROFORM	0.24 U	0.98 U	4.9 U	2.4 U	9.9 U
CIS-1,2-DICHLOROETHENE	0.2 U	0.79 U	4 U	2 U	8 U
CYCLOHEXANE	<b>0.17</b> J	<b>0.82</b> J	0.83 U	<b>1.7</b> J	39
DICHLORODIFLUOROMETHANE	2.9	<b>3.1</b> J	<b>10</b> J	0.59 U	2.4 U
ETHYLBENZENE	1.5	11	31	48	46
METHYLENE CHLORIDE	<b>0.46</b> J	0.42 U	2.1 U	1 U	4.2 U
N-HEPTANE	<b>0.31</b> J	4	2.2 U	<b>2</b> J	<b>18</b> J
N-HEXANE	<b>0.64</b> J	6.5	20	48	16 J
O-XYLENE	1.1	8.7	23	34	37
TETRACHLOROETHENE	7.7	59	2200	5.5 J	4.7 U
TOLUENE	35	290	1300	750	5000
TRANS-1,2-DICHLOROETHENE	0.2 U	0.79 U	4 U	2 U	8 U
TRICHLOROETHENE	0.075 U	<b>2.8</b> J	45	0.75 U	3 U
TRICHLOROFLUOROMETHANE	1.3	1.5 J	5.6 U	2.8 U	11 U
XYLENES, M & P	5	40	110	170	160
XYLENES, TOTAL	6.1	49	130	200	200

#### Notes:

VOC = volatile organic compounds

IA = indoor air sample

SS = sub-slab soil vapor sample

Samples analyzed by Test America by USEPA Method TO-15

Only detected compounds shown; detections are in bold.

Results in micrograms per cubic meter (µg/m<sup>3</sup>).

Qualifiers:

U = compound not detected above method detection limit

J = Estimated value

HONEPAHOOSICK-0000400

Table 1: 2011 Soil Vapor/Indoor Air VOC Results

Location Sample ID Sample Date	LS-IA-06-2 IA-06-2 01/26/11	LS-IA-07-2 IA-07-2 01/26/11	LS-SS-01-2 SS-01-2 01/26/11	LS-SS-01-2-D SS-01-2 01/26/11	LS-SS-02-2 SS-02-2 01/26/11
Parameter Name	Result Qualifier	Result Qualifier	Result Qualifier	Result Qualifier	Result Qualifier
1,1,1-TRICHLOROETHANE	0.55 U	2.7 U	9	8.7	0.27 U
1,2-DICHLOROETHANE	<b>1.3</b> J	0.61 U	0.49 U	0.49 U	0.061 U
1,2-DICHLOROETHENE (TOTAL)	0.79 U	4 U	22	21	<b>0.51</b> J
1,2-DICHLOROTETRAFLUOROETHANE	0.17 U	0.84 U	0.67 U	0.67 U	0.084 U
1,3,5-TRIMETHYLBENZENE	0.63 U	3.1 U	2.5 U	2.5 U	0.31 U
2,2,4-TRIMETHYLPENTANE	0.12 U	0.61 U	0.49 U	0.49 U	<b>0.28</b> J
4-ETHYLTOLUENE	0.63 U	3.1 U	2.5 U	2.5 U	0.31 U
BENZENE	1.6	<b>5.4</b> J	1.3 U	1.3 U	1.3
BROMODICHLOROMETHANE	0.67 U	3.4 U	11	<b>9.3</b> J	0.34 U
CARBON TETRACHLORIDE	0.63 U	3.1 U	2.5 U	2.5 U	<b>0.49</b> J
CHLOROFORM	0.49 U	2.4 U	26	24	0.24 U
CIS-1,2-DICHLOROETHENE	0.4 U	2 U	20	19	<b>0.51</b> J
CYCLOHEXANE	<b>0.35</b> J	<b>1.7</b> J	0.33 U	0.33 U	<b>0.31</b> J
DICHLORODIFLUOROMETHANE	<b>3.1</b> J	0. <b>5</b> 9 U	0.47 U	0.47 U	3
ETHYLBENZENE	4.2	32	0.49 U	0.49 U	<b>0.71</b> J
METHYLENE CHLORIDE	<b>0.71</b> J	1 U	0.83 U	14 U	1.7 U
N-HEPTANE	<b>0.7</b> J	<b>1.9</b> J	0. <b>89</b> U	0.89 U	<b>0.47</b> J
N-HEXANE	2.5	19	0.65 U	0.65 U	<b>0.57</b> J
O-XYLENE	3.4	23	1.7 U	1.7 U	<b>0.6</b> J
TETRACHLOROETHENE	22	530	14	12	7.5
TOLUENE	100	780	<b>5.2</b> J	<b>4.2</b> J	14
TRANS-1,2-DICHLOROETHENE	0.4 U	2 U	<b>1.7</b> J	<b>1.6</b> J	0.2 U
TRICHLOROETHENE	<b>0.57</b> J	7.7 J	1100	980	4.5
TRICHLOROFLUOROMETHANE	<b>1.4</b> J	2.8 U	2.2 U	2.2 U	1.5
XYLENES, M & P	15	110	0.8 U	0.8 U	2.2
XYLENES, TOTAL	18	130	5.2 U	5.2 U	2.8

#### Notes:

VOC = volatile organic compounds

IA = indoor air sample

SS = sub-slab soil vapor sample

Samples analyzed by Test America by USEPA Method TO-15

Only detected compounds shown; detections are in bold.

Results in micrograms per cubic meter (µg/m<sup>3</sup>).

Qualifiers:

U = compound not detected above method detection limit

J = Estimated value

HONEPAHOOSICK-0000401

Table 1: 2011 Soil Vapor/Indoor Air VOC Results

Location Sample ID Sample Date	SS-	S-04-2 04-2 26/11	SS-	S-05-2 05-2 26/11	SS	S-06-2 -06-2 26/11	SS-	S-07-2 -07-2 26/11
Parameter Name	Result	Qualifier	Result	Qualifier	Result	Qualifier	Result	Qualifier
1,1,1-TRICHLOROETHANE	0.27	U	12		0.59	) J	1.4	J
1,2-DICHLOROETHANE	0.061	U	0.061	U	0.061	U	0.26	U
1,2-DICHLOROETHENE (TOTAL)	0.4	U	0.4	U	0.4	ł U	110	)
1,2-DICHLOROTETRAFLUOROETHANE	0.084	U	0.084	U	0.084	ł U	0.36	5 U
1,3,5-TRIMETHYLBENZENE	3.6		2.2		1.8	}	1.3	U
2,2,4-TRIMETHYLPENTANE	0.061	U	0.061	U	0.061	. U	0.26	U
4-ETHYLTOLUENE	1.2		2.3		0.49	<b>)</b> J	1.3	U
BENZENE	0.52	J	1.1		0.54	ŀЈ	0.68	3 U
BROMODICHLOROMETHANE	0.34	U	0.34	U	0.34	ł U	1.4	U
CARBON TETRACHLORIDE	0.44	J	0.38	J	0.33	J	1.3	U
CHLOROFORM	0.24	U	0.24	U	0.24	ł U	1	U
CIS-1,2-DICHLOROETHENE	0.2	U	0.2	U	0.2	2 U	110	)
CYCLOHEXANE	0.21	J	0.3	J	0.35	5 J	0.18	3 U
DICHLORODIFLUOROMETHANE	3.1		2.9		2.9	)	3.1	. J
ETHYLBENZENE	0.59	J	3.4		1.9	)	0.26	5 U
METHYLENE CHLORIDE	1.7	U	1.7	U	1.7	U U	0.44	U
N-HEPTANE	0.7	J	1.4		1.3	3	0.47	'U
N-HEXANE	0.56	J	0.97		0.49	<b>)</b> J	0.35	U
O-XYLENE	1.1		2.2		2.4	ļ.	0.92	2 U
TETRACHLOROETHENE	2.6		160	ı	13	3	17	,
TOLUENE	9.2		14		13	3	3.8	}
TRANS-1,2-DICHLOROETHENE	0.2	U	0.2	U	0.2	2 U	0.84	U
TRICHLOROETHENE	0.75	J	40	ı	2.4	ļ	560	)
TRICHLOROFLUOROMETHANE	1.5		1.5		1.5	5	1.6	J
XYLENES, M & P	1.9	J	3.8		9.9	)	0.43	U
XYLENES, TOTAL	3	ı	6	I	12	2	2.8	3 U

#### Notes:

VOC = volatile organic compounds

IA = indoor air sample

SS = sub-slab soil vapor sample

Samples analyzed by Test America by USEPA Method TO-15

Only detected compounds shown; detections are in bold.

Results in micrograms per cubic meter (µg/m<sup>3</sup>).

Qualifiers:

U = compound not detected above method detection limit

J = Estimated value

Mr. Christopher O'Neill, P.E. June 2011

Mr. Christopher O'Neill, P.E. MACTEC Project: 3410100802

### ATTACHMENT A JANUARY 2011 FIELD DATA RECORDS

		INDOOR	AIR SAN	MPLING RECO	RD _				
PROJECT NAME:	Forr	ner Furon Sites - Liber	ty Street	LOCATION ID:	15	DATE: 6]-2	26-2011		
PROJECT NO./TAS	SK NO.:	341010080	)2	CLIENT:	Honeyw	ell			
PROJECT LOCATION: Hoosick Falls, New York SAMPLER NAME: Brandon Shaw									
WEATHER CONDI	WEATHER CONDITIONS (AM): 30 +, partly cloudy. SAMPLER SIGNATURE:								
WEATHER CONDITIONS (PM): 301F, dark CHECKED BY: BJS DATE: 3/31/2011									
		SUMM	A Canister	Record Information					
INDOOR A	AIR	INDOOR A	AIR	INDOOR A	AIR	ASSOCIATED A AIR	MBIENT		
Flow Regulator Number:	3175	Flow Regulator Number:	4189	Flow Regulator Number:	3736	Flow Regulator Number:	2925 <del>3433</del>		
Flow Rate (mL/min):	~13	Flow Rate (mL/min):	v12	Flow Rate (mL/min):	~13	Flow Rate (mL/min):	~/D		
Canister Serial Number:	3072	Canister Serial Number:	2537	Canister Serial Number:	2693	Canister Serial Number:	4022		
Start Date/Time: 01 - 2	1130	Start Date/Time: 61-2	1132	Start Date/Time: 0(-2	1128	Start Date/Time: 01-2	1116		
Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-27		
Stop Date/Time: 61-26	-2011 <del>725</del> 1838	Stop Date/Time: 01-21	1939	Stop Date/Time: 01-2	1949	Stop Date/Time:	6-2011 1911		
Stop Pressure ("Hg):	-4	Stop Pressure ("Hg):	-4	Stop Pressure ("Hg):	-4	Stop Pressure ("Hg):	-Z		
Sample ID: LS-I/	4-01-2	Sample ID: LS -IA	-02-2	Sample ID: とS ーエ	A -03-2	Sample ID: LS — A	-04-2		
		Otl	her Samplin	g Information:					
Story/Level:	FIXT	Story/Level:	first-	Story/Level:	Filst	Direction from Building:	West.		
Room:	Kitchen	Room: Break vov	• (7, 5	Room:	office	Distance from Building:	~1b'		
Potential Vapor Entry Points:	none	Potential Vapor Entry Points:	1000	Potential Vapor Entry Points:	mhdov	Distance from Roadway:	~150'		
Floor Surface:	Levolum	Floor Surface:	over where	Floor Surface:	tile	Ground Surface:	Snew		
Noticable Odor:	hone	Noticable Odor:	hone	Noticable Odor:	hire	Noticable Odor:	vine		
PID Reading (ppb):	325	PID Reading (ppb):	4600	PID Reading (ppb):	5650	PID Reading (ppb):	20.		
Intake Height:	~4.5'	Intake Height:	~5'	Intake Height:	~4'	Intake Height Above Ground Surface:	-31		
Indoor Air Temp:	70:F	Indoor Air Temp:	70°F	Indoor Air Temp:	76%	Intake Tubing Used?	hi.		
Comments/Locatio		figure 1	for	bafion	- 81	cetil.			
FIGURE 4-19 INDOOR AIR SAMPLING RECORD									
511 Congress St	reet, Portlan	d, ME 04101	NY	SDEC QUALIT	Y ASSUI	RANCE PROJEC	CT PLAN		

		INDOOR	AIR SAI	MPLING RECO	RD				
PROJECT NAME:	For	ner Furon Sites - Liber	ty Street	LOCATION ID:	L	DATE:	-26-2011		
PROJECT NO./TAS	SK NO.:	341010080	)2	CLIENT:	Honeyw	ell			
PROJECT LOCATI	ON:	Hoosick Falls, New Y	ork	SAMPLER NAM	E: Brai	ndon Shaw			
WEATHER CONDI	TIONS (AM)	31 F, DO	artly d	ow Sampler Sign	ATURE!				
WEATHER CONDITIONS (AM): 31 F, party clow sampler signature.  WEATHER CONDITIONS (PM): 31 F, direction of the checked by: BS Date: 3/31/2010									
SUMMA Canister Record Information									
INDOOR A	AIR	INDOOR A	AIR	INDOOR A	AIR	ASSOCIATED A	MBIENT		
Flow Regulator Number:	3933	Flow Regulator Number:	5196	Flow Regulator Number:	5201	Flow Regulator Number:	2925		
Flow Rate (mL/min):	~13	Flow Rate (mL/min):	~10	Flow Rate (mL/min):	~12	Flow Rate (mL/min):	~10		
Canister Serial Number:	4022	Canister Serial Number:	5164	Canister Serial Number:	2598	Canister Serial Number:	2708		
	126	istart Hare/Time:	6-2011 150	Start Date/Time: 0 \ - Z	6-2011 1140	Start Date/Time:	e-2011		
Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-70	Start Pressure ("Hg):	-27	Start Pressure ("Hg):	-27		
Stop Date/Time: 01-2	1901	Stop Date/Time: D   -Z	6-2011 12003	Stop Date/Time: 01-3	1909	Stop Date/Time:	1911		
Stop Pressure ("Hg):	<b>75</b>	Stop Pressure ("Hg):	-10	Stop Pressure ("Hg):	-5	Stop Pressure ("Hg):	-2		
Sample ID: LS-I4	-04-2	Sample ID: LS — IA	1-06-2	Sample ID: LS-IA	-67-2	Sample ID: LS -AA	-01-2		
		Otl	her Samplir	ng Information:					
Story/Level:	FIRH	Story/Level:	fir+	Story/Level:	filst	Direction from Building:	nest		
Room:	QA Lab Office	Room:	office	Room:	Color, mix Round Hall	Distance from Building:	~ 1b1		
Potential Vapor Entry Points:	Hone	Potential Vapor Entry Points:	imhden	Potential Vapor Entry Points:	loading	Distance from Roadway:	~150'		
Floor Surface:	lensteum	Floor Surface:	tile	Floor Surface:	rubber on Concrete	Ground Surface:	Show		
Noticable Odor:	nne	Noticable Odor:	yes	Noticable Odor:	yes	Noticable Odor:	nonè		
PID Reading (ppb):	8993	PID Reading (ppb):	5200.	PID Reading (ppb):	5509	PID Reading (ppb):	40.		
Intake Height:	-4'	Intake Height:	~51	Intake Height:	~5 <sup>1</sup>	Intake Height Above Ground Surface:	431		
Indoor Air Temp:	76 F	Indoor Air Temp:	70°F	Indoor Air Temp:	-68F	Intake Tubing Used?	no.		
Comments/Locatio	_	fer to	Figure	1 for	locat	ion stel	Th.		
FIGURE 4-19 INDOOR AIR SAMPLING RECORD									

511 Congress Street, Portland, ME 04101

NYSDEC QUALITY ASSURANCE PROJECT PLAN

	SU	JB SLAD AND I	NDOOR .	AIR SAMPLING	G RECOR	<b>D</b>	
PROJECT NAME:	Former 1	Furon Sites - Liberty	Street Site	LOCATION ID:	LS	DATE: <u>0</u> /-	-26-2011
PROJECT NO./TAS	SK NO.:	3410100802, 21	00	CLIENT:	Honeywell		
PROJECT LOCATI	ON:	Hoosick Falls, New Yo		SAMPLER NAM	E: <b>Bra</b>	inden Shaw	<u>′</u>
WEATHER CONDI	TIONS (AM)	30 F, our	tly dov	SAMPLER SIGN	ATURE		
WEATHER CONDI	TIONS (PM):			CHECKED BY:		DATE: 3/	31/2011
		SUMMA	A Canister 1	Record Information		-	
SUB-SLAB SOIL SAMPLI		SUB-SLAB SOIL SAMPLI		SUB-SLAB SOIL SAMPLI		SUB-SLAB SOIL SAMPLI	
Flow Regulator Number:	5180	Flow Regulator Number:	3946	Flow Regulator Number:	5186	Flow Regulator Number:	3447
Flow Rate (mL/min):	~10	Flow Rate (mL/min):	~10	Flow Rate (mL/min):	~15	Flow Rate (mL/min):	-12
Canister Serial Number:	4465	Canister Serial Number:	2624	Canister Serial Number:	2644	Canister Serial Number:	4240
Start Date/Time: 01-	26-2611 1130		16-2011 1130	Start Date/Time:	1202	Start Date/Time: 01-2	10-2011 1127
Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-28	Start Pressure ("Hg):	-30.
Stop Date/Time: 01-20	1956	Stop Date/Time: 2 -2	.6-2011 1956	Stop Date/Time: 0]-2	6-2eU 1907	Stop Date/Time: 01-2	6-2011 1961
Stop Pressure ("Hg):	-4	Stop Pressure ("Hg):	-10	Stop Pressure ("Hg):		Stop Pressure ("Hg):	25
Sample ID: LS -SS -	-01-2	Sample ID: LS -SS -	01-2-1	Sample ID: LS - SS.	-02 -2	Sample ID: LS-5	-04-2
		Otl	her Samplin	g Information:			
Room:	electura	Room:	electrial	Room:	ware horse	, Room:	offie
Floor Slab Thickness:	v fr	Floor Slab Thickness:	۱° ه ۸	Floor Slab Thickness:	~ 4"1	Floor Slab Thickness:	~ <b>b</b> 34
Potential Vapor Entry Points:	None	Potential Vapor Entry Points:	nene	Potential Vapor Entry Points:	orants.	Potential Vapor Entry Points:	none
Floor Surface:	concrete	Floor Surface:	conente	Floor Surface:	tsphalt.	Floor Surface:	Censtern
Noticable Odor:	NK	Noticable Odor:	NA	Noticable Odor:	NA	Noticable Odor:	NA -
PID Reading (ppb):	1300	PID Reading (ppb):	1300	PID Reading (ppb):	780	PID Reading (ppb):	1505
Intake Depth:	-1,5"	Intake Depth:	ù7.5"	Intake Depth:	~ 7.512	Intake Depth:	~7.5"
Helium Test Conducted?	70.	Helium Test Conducted?	ND	Helium Test Conducted?	M	Helium Test Conducted?	No
Comments/Locatio	n Sketch:	to Figu	ive 1	for low	fin	sketch	
MA 511 Congress St		rec					

SUB SLAD AND INDOOR AIR SAMPLING RECORD										
PROJECT NAME:	Former	Furon Sites - Liberty	Street Site	LOCATION ID:	LS	DATE: 0/-	26-2011			
PROJECT NO./TAS	SK NO.:	3410100802, 21	00	CLIENT:	Honeywell					
PROJECT LOCATI	ON:	Hoosick Falls, New Yo	ork	SAMPLER NAM	е: <u>В</u> уи	ndon show				
WEATHER CONDI	TIONS (AM)	: 307, pin	41/ clou	dV sampler sign	ATURE		<u> </u>			
WEATHER CONDI	TIONS (PM)	31'F, dave	· ·	CHECKED BY:	BJS	DATE: 3).	31/20 N			
	SUMMA Canister Record Information									
SUB-SLAB SOIL		SUB-SLAB SOIL		SUB-SLAB SOIL	1	ŠUB-SLAB SOIL				
SAMPLI Flow Regulator		SAMPLI Flow Regulator	<u> </u>	SAMPLI Flow Regulator		SAMPLI Flow Regulator	£			
Number:	4516	Number:	5204	Number:	2666	Number:				
Flow Rate (mL/min):	-10	Flow Rate (mL/min):	n 13	Flow Rate (mL/min):	~ lo	Flow Rate (mL/min):				
Canister Serial Number:	3833	Canister Serial Number:	4123	Canister Serial Number:	3527	Canister Strial Number:				
Start Date/Time: 0 \ -2	6-204 1148	Start Date/Time: 0\-2	1155	Start Date/Time:	26-2011 1207	Start Date/Time:	03/3//2011			
Start Pressure ("Hg):	/ho	Start Pressure ("Hg):	-30	Start Pressure ("Hg):	-26	Start Pressure ("Ng):	•			
Stop Date/Time: 0   - 2	6-2011 1945	Stop Date/Time: 01-7	26-211	Stop Date/Time: 01-20	1850	Stop Date/Time:				
Stop Pressure ("Hg):	-4	Stop Pressure ("Hg):	-5	Stop Pressure ("Hg):	-5	Stop Pressure ("Hg):	\ .			
Sample ID: LS - 55-	-06-2	Sample ID: L5-55	-07-2	Sample ID: LS-SS	-05-2	Sample ID:				
		Ot	her Samplir	ng Information:	٠.		\			
Room:	office	Room:	Hallway	Room:	office with IA-02	Room: VAS	131/2011			
Floor Slab Thickness:	~6"	Floor Slab Thickness:	~7°°	Floor Slab Thickness:	~ b"	Floor Slab Thickness:	' '			
Potential Vapor Entry Points:	vone	Potential Vapor Entry Points:	none	Potential Vapor Entry Points:	hone	Potential Vapor Entry Points:				
Floor Surface:	tile	Floor Surface:	Rubberon	Floor Surface:	Cruleum	Floor Surface:				
Noticable Odor:	3 tight	Noticable Odor:	NA	Noticable Odor:	NA	Noticable Odor:	<b>\</b>			
PID Reading (ppb):	980	PID Reading (ppb):	1132	PID Reading (ppb):	780	PID Reading (ppb):				
Intake Depth:	~715"	Intake Depth:	~7,5"	Intake Depth:	-7.5"	Intake Depth:				
Helium Test Conducted?	100	Helium Test Conducted?	No.	Helium Test Conducted?	No-	Helium Test Conducted?				
Comments/Location			. 1		<b>)</b>					
	R	eter to til	jure:	I for lo	cation	sketch				
	•	-	U							
	4 <b>C</b>	ΓΕС								
511 Congress St										

#### 1 Liberty Stroot

#### NEW YORK STATE DEPARTMENT OF HEALTH INDOOR AIR QUALITY QUESTIONNAIRE AND BUILDING INVENTORY CENTER FOR ENVIRONMENTAL HEALTH

This form must be completed for each residence involved in indoor air testing.


Preparer's Name Ryaw Markowski Date/Time Prepared 1/25/11 @ 1500
Preparer's Affiliation MALTEL Phone No. 207-831-2131
Purpose of Investigation SOIL VAPOR Intrusion Investigation
1. OCCUPANT:
Interviewed: YN N
Last Name: BEANMONT First Name: YJ
Address: 1 Liberty Street
County: <u>Densselger</u> Lo Hoosick Falls, NY
Home Phone: Office Phone:
Number of Occupants/persons at this location Age of Occupants We will be a second of Occupants Age of Occupants
2. OWNER OR LANDLORD: (Check if same as occupant $\underline{NA}$ )
Interviewed: Y N
Last Name:First Name:
Address:
County:
Home Phone: Office Phone:
3. BUILDING CHARACTERISTICS
Type of Building: (Circle appropriate response)
Residential School Commercial/Multi-use Plant fractory Industrial Church Other:

1

If the property is residential, type? (Circle appropriate response)	Liberty street
Ranch Raised Ranch Cape Cod Contemporary Duplex Modular  Raised Ranch Apartment House Colonial Contemporary Mobile Home Townhouses/Condos Other:	
If multiple units, how many?	
If the property is commercial, type?	
Business Type(s) Plastics + Continy Trylos	
Does it include residences (i.e., multi-use)? Y(N) If yes, how many? MA	
Other characteristics:	
Number of floors   Building age 1948	
Is the building insulated? Y(N) How air tight? Tight / Average Not Tight	t)
4. AIRFLOW 3 Not	
Use air current tubes or tracer smoke to evaluate airflow patterns and qualitatively des	scribe:
Airflow between floors	
Airflow near source	
Outdoor air infiltration	
	1 NA W
Infiltration into air ducts	of A.

5. BASEMENT AND CONSTRUC	CTION CHARAC	TERISTICS (	Circle all that ap	ply)	·
a. Above grade construction:	wood frame	concrete	stone	brick	
b. Basement type:	full 💮	crawlspace	slab	other	7
c. Basement floor.	concrete A	随EMI	stone	other	
d. Basement floor:	uncovered	covered	covered with _		1
e. Concrete floor:	unsealed (	sealed	sealed with		
f. Foundation walls:	poured	block	stone	other	
g. Foundation walls:	unsealed	sealed	sealed with		
h. The basement is:	wet	damp	dry	moldy Rin	1/26/11
i. The basement is:	finished	unfinished	partially finish	moldy Rin	126/11
j. Sump present?	YN				
k. Water in sump? Y/N	not applicable				
Basement/Lowest level depth below	grade: 🖋 (	feet)			
Identify potential soil vapor entry po	oints and approxi	mate size (e.g.,	cracks, utility	ports, drains)	
2					
SEE uparton	Map / Rigi	unos to	identity	ponts	
6. HEATING, VENTING and AIR		• •			
Type of heating system(s) used in th	is building: (circl	e all that apply	– note primar	<b>y</b> )	•
Hot air circulation Space Heaters	Heat pump Stream radiation	n Radiar	ater baseboard at floor	ρ	().
Electric baseboard //26/11	Wood stove	Outdo	or wood boiler	Other Many	Liver Hem
The primary type of fuel used is:				Other Propert	La-10
Natural Gas Electric	Fuel Oil			•	0 = <b>30</b> p
		Kerose Solar	ene		
Wood	Propane Coal	Kerose Solar	ene		y - sep
	Propane		ene		· · · ·
Wood	Propane Coal	Solar		Other	
Wood  Domestic hot water tank fueled by:  Boiler/furnace located in:  Baser	Propane Coal Propane Outdoo	Solar	Floor	Other	
Wood  Domestic hot water tank fueled by:  Boiler/furnace located in:  Baser	Propane Coal Propane Outdoo	Solar ors Main	Floor	•	

Are there air distribution ducts present?



Liberty St.

Describe the supply and cold air return ductwork, and its condition where visible, including whether there is a cold air return and the tightness of duct joints. Indicate the locations on the floor plan diagram.

$\sum_{i} f_{i} = \int_{0}^{\infty} $
Ductuon 16 Afforms to be functioning properly Li sorling, tight + wellows together
JOHN 15 HYMF & WOLDERS 109 PIMC
7. OCCUPANCY
7. OCCUPANCY  Is basement/lowest level occupied? Full-time Occasionally Seldom Almost Never
Level General Use of Each Floor (e.g., familyroom, bedroom, laundry, workshop, storage)
Basement
1st Floor Offices, Brookrown, Controlls, Production, Bathrooms, + worker
2 <sup>nd</sup> Floor
3 <sup>rd</sup> Floor Rim
4 <sup>th</sup> Floor
74
8. FACTORS THAT MAY INFLUENCE INDOOR AIR QUALITY
a. Is there an attached garage?
b. Does the garage have a separate heating unit?  Y/N(NA)
c. Are petroleum-powered machines or vehicles stored in the garage (e.g., lawnmower, atv, car)  Y/N  Please specify  Please specify
d. Has the building ever had a fire?  (Y)N When? NOT Structure, 2010
e. Is a kerosene or unvented gas space heater present? (Y) N Where? Direct from Proper Mark
f. Is there a workshop or hobby/craft area?  (Y) N Where & Type? Factory
g. Is there smoking in the building?  YN How frequently?
h. Have cleaning products been used recently? (Y)N When & Type? Tolucal Regular basis
i. Have cosmetic products been used recently?  Y(N) When & Type?
SAS 201

Liberty ct.


			•	*		
j. Has painting/st	aining been done in the last 6 mo	nths? YN	Where & When?		2010	
k. Is there new ca	rpet, drapes or other textiles?	(Y)/ N	Where & When?	Doc.	2010-	Inc
l. Have air freshe	ners been used recently?	Y (N	When & Type?		·.	
m. Is there a kitch	hen exhaust fan?	YN	If yes, where vent	ed?		٠.
n. Is there a bath	room exhaust fan?	YN	If yes, where vent	ed?	<del> </del>	
o. Is there a cloth	es dryer?	Y (N	If yes, is it vented	outside? Y	'N	
p. Has there been	a pesticide application?	M (Y)	When & Type?	Suran AROURD	ZOID Burlor-W	•
Are there odors in If yes, please des		Ý M			ノ -	٠
(e.g., chemical manu	ing occupants use solvents at wor facturing or laboratory, auto mech ticide application, cosmetologist	anic or auto body				· · ·
If yes, what types	of solvents are used? Acc	tone -	Toluony +	VARIOUS	Typos	
If yes, are their clo	othes washed at work?	Y/N	)	of De	growsns	
Do any of the build response)	ing occupants regularly use or w	ork at a dry-cle	aning service? (Cir	cle appropri	ate	: :
Yes, use dry	-cleaning regularly (weekly) -cleaning infrequently (monthly or a dry-cleaning service	less) (	No Unknown			•
Is there a radon mi	tigation system for the building/s or passive? Active/Passiv		Date of Installation	on:		٠.
9. WATER AND SI	EWAGE			•		
Water Supply:	Public Water Drilled Well	Driven Well	Dug Well C	Other:		
Sewage Disposal:	Public Sewer Septic Tank	Leach Field	Dry Well C	Other:	A-Paris	
10. RELOCATION	INFORMATION (for oil spill r	esidential emerg	gency)		·	
a. Provide reas	ons why relocation is recommend	ded:		,		
b. Residents ch	oose to: remain in home reloc	ate to friends/fan	nily relocate t	o hotel/mote	el .	
c. Responsibilit	y for costs associated with reimb	oursement expla	ined? Y/N			
d. Relocation p	ackage provided and explained	o residents?	Y/N			
·.			<b>√</b>	5		
•				21-6011		

Liberty St.

#### 11. FLOOR PLANS

Draw a plan view sketch of the basement and first floor of the building. Indicate air sampling locations, possible indoor air pollution sources and PID meter readings. If the building does not have a basement, please note.


#### Basement:



#### 12. OUTDOOR PLOT

Draw a sketch of the area surrounding the building being sampled. If applicable, provide information on spill locations, potential air contamination sources (industries, gas stations, repair shops, landfills, etc.), outdoor air sampling location(s) and PID meter readings.

Also indicate compass direction, wind direction and speed during sampling, the locations of the well and septic system, if applicable, and a qualifying statement to help locate the site on a topographic map.



#### 13. PRODUCT INVENTORY FORM

Make & Model of field instrument used: pph Rac 3000 - Ping

List specific products found in the residence that have the potential to affect indoor air quality.

Location	Product Description	Size (units)	Condition*	Chemical Ingredients	Field Instrument Reading (units)	Photo **  Y/N
157 Floor	Riuson Pignoti	4,500g	ins U		1600ppm	V
Ist Floor	Prints Prinn, Evans)	£40, 19+	1 y/u	<del> </del>	~10-20pm	Y
Ist Floor	Spany Port, Gloss, Fush	£35, 12,	2 4/40	3.4	F10-20112	Y
KT Floor	Degrassens Action, Lubris	1,7/00,14	04/110	Lubrisil - S TLE, PLE	250-450pp	V
1st Floor	· · · · · · · · · · · · · · · · · · ·	150,	W/NO		10-45pm	Y
15+ Floor	Lub. oil	3,55g	1 4		10.500	Ŵ
·-		ì				
		:				
• •						
			bas			
			1 px			

<sup>\*</sup> Describe the condition of the product containers as Unopened (UO), Used (U), or Deteriorated (D)

PK 03-31-2011.

P:\Sections\SIS\Oil Spills\Guidance Docs\OSR-3.doc

٠.


<sup>\*\*</sup> Photographs of the **front and back** of product containers can replace the handwritten list of chemical ingredients. However, the photographs must be of good quality and ingredient labels must be legible.

Mr. Christopher O'Neill, P.E. June 2011

Mr. Christopher O'Neill, P.E. MACTEC Project: 3410100802

#### ATTACHMENT B

#### PERMANENT SUB-SLAB SOIL VAPOR POINT DIAGRAM



#### Permanent Sub Slab Soil Vapor Point

PORT2011013b

Mr. Christopher O'Neill, P.E. June 2011

Mr. Christopher O'Neill, P.E. MACTEC Project: 3410100802

## ATTACHMENT C DATA USABILITY SUMMARY REPORT

## DATA USABILITY SUMMARY REPORT JANUARY 2011 INDOOR AIR AND SUB-SLAB VAPOR SAMPLING FORMER HONEYWELL SITE- LIBERTY ST HOOSICK FALLS, NEW YORK

#### 1.0 INTRODUCTION

Indoor air and sub-slab vapor samples were collected at the Former Honeywell Hoosick Falls – Liberty Street Site (Site) in Hoosick Falls, New York in January 2011 and submitted for off-site laboratory analysis. Samples were analyzed by TestAmerica Laboratories located in South Burlington, Vermont (TAL-BUR). Results were reported in sample delivery group (SDG) 220-3615.

A listing of samples included in this Data Usability Summary Report (DUSR) is presented in Table 1. A summary of the final analytical results is presented in Table 2. A summary of samples qualified during this review is presented in Table 3. Samples were analyzed by the following methods:

Volatile organic compounds (VOCs) by USEPA Method TO-15

Deliverables for the off-site laboratory analyses included a Category B deliverable as defined in the New York State Department of Environmental Conservation (NYSDEC) Analytical Services Protocols (NYSDEC, 2005). Results were reported in units of ppbv and  $\mu g/m^3$  in the lab reports. The unit used in reporting data for this project is  $\mu g/m^3$ .

A project chemist review was completed based on NYSDEC Division of Environmental Remediation guidance for Data Usability Summary Reports (NYSDEC, 2010). USEPA Region II quality control (QC) limits were used during the data evaluation unless noted otherwise (USEPA, 2006). The project chemist review included evaluations of sample collection, data package completeness, holding times, QC data (blanks, instrument calibrations, duplicates, surrogate recovery, and control sample recovery), data transcription, electronic data reporting, calculations, and data qualification.

The following laboratory or data validation qualifiers are used in the final data presentation.

U = target analyte is not detected at the reporting limit J = concentration is estimated

Results are interpreted to be usable as reported by the laboratory unless discussed in the following sections.

#### 2.0 VOLATILE ORGANIC COMPOUNDS (VOCS)

#### VOC - Blanks

Methylene chloride was observed in the method blank associated with a subset of samples at a concentration of  $0.57~\mu g/m^3$ . An action level of  $2.85~\mu g/m^3$  was established at five times the concentration reported in the blank. Methylene chloride detections in associated samples LS-SS-

Page 1 of 2

01-2-D, LS-SS-02-2, LS-SS-04-2, LS-SS-05-2, and LS-SS-06-2 were below the established action levels and were qualified as non-detect (U) at the reporting limit.

Field Sample	QC Code	Lab ID	Compound	Dilution Factor	Final Result (µg/m³)	Final Qual	Lab Result (µg/m³)	Lab Qual
LS-SS-01-2-D	FD	200-3615-22	Methylene Chloride	8	14	U	5.4	JВ
LS-SS-02-2	FS	200-3615-23	Methylene Chloride	1	1.7	U	0.54	Љ
LS-SS-04-2	FS	200-3615-24	Methylene Chloride	1	1.7	U	0.63	ЛВ
LS-SS-05-2	FS	200-3615-25	Methylene Chloride	1	1.7	U	0.69	Љ
LS-SS-06-2	FS	200-3615-26	Methylene Chloride	1	1.7	U	0.80	Љ

#### VOC - Sample Reporting

Dilution analyses were performed on the following samples due to elevated concentrations of target compounds. Reporting limits for target compounds that were not detected in samples are elevated due to dilution.

Field Sample ID	QC Code	Lab ID	Dilution Factor
LS-IA-01-2	FS	200-3615-14	4
LS-IA-02-2	FS	200-3615-15	20
LS-IA-03-2	FS	200-3615-16	10
LS-IA-04-2	FS	200-3615-18	40.5
LS-IA-06-2	FS	200-3615-19	2
LS-IA-07-2	FS	200-3615-20	10
LS-SS-01-2	FS	200-3615-21	8
LS-SS-01-2-D	FD	200-3615-22	. 8
LS-SS-07-2	FD	200-3615-27	4.26

#### Reference:

New York State Department of Environmental Conservation (NYSDEC), 2005. "Analytical Services Protocols"; July 2005.

New York State Department of Environmental Conservation (NYSDEC), 2010. "Technical Guidance for Site Investigation and Remediation-Appendix 2B"; DER-10; Division of Environmental Remediation; May 2010.

U.S. Environmental Protection Agency (USEPA), 2006. "Validating Air Samples Volatile Organic Analysis of Ambient Air in Canister by Method TO-15"; USEPA Region II; HW-31; Revision #4; October 2006.

Data Validation: Bradley B. LaForest, NRCC-EAC

Reviewed by Chris Ricardi, NRCC-EAC

Date: 4/7/11

# TABLE 1 DATA USABILITY SUMMARY REPORT JANUARY 2011 INDOOR AIR AND SUB-SLAB VAPOR SAMPLING FORMER HONEYWELL SITE HOOSICK FALLS, NEW YORK

SDG	Sample ID	Lab ID	Sample Date	Sample Type	Method
200-3615	LS-IA-01-2	200-3615-14	1/26/2011	REG	TO-15
200-3615	LS-IA-02-2	200-3615-15	1/26/2011	REG	TO-15
200-3615	LS-IA-03-2	200-3615-16	1/26/2011	REG	TO-15
200-3615	LS-AA-01-2	200-3615-17	1/26/2011	REG	TO-15
200-3615	LS-IA-04-2	200-3615-18	1/26/2011	REG	TO-15
200-3615	LS-IA-06-2	200-3615-19	1/26/2011	REG	TO-15
200-3615	LS-IA-07-2	200-3615-20	1/26/2011	REG	TO-15
200-3615	LS-SS-01-2	200-3615-21	1/26/2011	REG	TO-15
200-3615	LS-SS-01-2 <b>-</b> D	200-3615-22	1/26/2011	FD	TO-15
200-3615	LS-SS-02-2	200-3615-23	1/26/2011	REG	TO-15
200-3615	LS-SS-04-2	200-3615-24	1/26/2011	REG	TO-15
200-3615	LS-SS-05-2	200-3615-25	1/26/2011	REG	TO-15
200-3615	LS-SS-06-2	200-3615-26	1/26/2011	REG	TO-15
200-3615	LS-SS-07-2	200-3615-27	1/26/2011	REG	TO-15

## TABLE 2 DATA USABILITY SUMMARY REPORT JANUARY 2011 INDOOR AIR AND SUB-SLAB VAPOR SAMPLING (µg/m3) FORMER HONEYWELL SITE HOOSICK FALLS, NEW YORK

	<u></u>	Field Sample ID	LS-AA-01-2	LS-IA-01-2	LS-IA-02-2	LS-IA-03-2	LS-IA-04-2	LS-IA-06-2	LS-IA-07-2
•		Location	AA-01-2	IA-01-2	IA-02-2	IA-03-2	IA-04-2	IA-06-2	IA-07-2
		Sample Date	1/26/2011	1/26/2011	1/26/2011	1/26/2011	1/26/2011	1/26/2011	1/26/2011
Units	Method	Parameter Name							
ug/m3	TO15	1,1,1-Trichloroethane	0.27 U	1.1 U	5.5 U	2.7 U	11 U	0.55 U	2.7 U
ug/m3	TO15	1,1,2,2-Tetrachloroethane	0.34 U	1.4 U	6.9 U	3.4 U	. 14 U	0.69 U	3.4 U
ug/m3	TO15	1,1,2-Trichloroethane	0.27 U	1.1 U	5.5 U	2.7 U	11 U	0.55 U	2.7 U
ug/m3	TO15	1,1-Dichloroethane	0.053 U	0.21 U	1.1 U	0.53 U	2.1 U	0.11 U	0.53 U
ug/m3	TO15	1,1-Dichloroethene	0.059 U	0.24 U	1.2 U	0.59 U	2.4 U	0.12 U	0.59 U
ug/m3	TO15	1,2-Dibromoethane	0.092 U	0.37 U	1.8 U	0.92 U	3.7 U	0.18 U	0.92 U
ug/m3	TO15	1,2-Dichloroethane	0.061 U	0.24 U	1.2 U	0.61 U	2.5 U	1.3 J	0.61 ป
ug/m3	TO15	1,2-Dichloroethene, Total	0.4 U	1.6 U	7.9 U	4 U	16 U	0.79 U	4 U
ug/m3	TO15	1,2-Dichloropropane	0.074 U	0.3 U	1.5 U	0.74 U	3 U	0.15 U	0.74 U
ug/m3	TO15	1,2-Dichlorotetrafluoroethane	0.084 U	0.34 U	<b>11</b> J	0.84 U	3.4 U	0.17 U	0.84 U
ug/m3	TO15	1,3,5-Trimethylbenzene	0.31 U	1.3 U	6.3 U	3.1 U	13 U	0.63 U	3.1 U
ug/m3	TO15	1,3-Butadiene	0.06 U	0.24 U	1.2 U	0.6 U	2.4 U	0.12 U	0.6 U
ug/m3	TO15	2,2,4-Trimethylpentane	0.061 U	0.24 U	1.2 U	0.61 U	2.5 U	0.12 U	0.61 U
ug/m3	TO15	3-Chloropropene	0.091 U	0.36 U	1.8 U	0.91 U	3.7 U	0.18 U	0.91 U
ug/m3	TO15	4-Ethyltoluene	0.31 U	1.3 U	6.3 U	3.1 U	13 U	0.63 U	3.1 U
ug/m3	TO15	Benzene	1.1 、	2.7	4.6 J	4.9 J	6.9 J	1.6	5.4 J
ug/m3	TO15	Bromodichloromethane	0.34 U	1.3 U	6.7 U	3.4 U	14 U	0.67 U	3.4 U
ug/m3	TO15	Bromoethene(Vinyl Bromide)	0.22 U	0.87 U	4.4 U	2.2 U	8.9 U	0.44 U	2.2 U
ug/m3	TO15	Bromoform	0.52 U	2.1 U	10 U .	5.2 U	21 U	1 U	5.2 U
ug/m3	TO15	Bromomethane	0.054 U	0.22 U	1.1 U	0.54 U	2.2 U	0.11 U	0.54 U
ug/m3	TO15	Carbon tetrachloride	0.5 J	1.3 U	6.3 U	3.1 U	13 U	0.63 U	3.1 U
ug/m3		Chloroethane	0.26 U	1.1 U	5.3 U	2.6 U	11 U	0.53 U	2.6 U
ug/m3	TO15	Chloroform	0.24 U	0.98 U	4.9 U	2.4 U	9.9 U	0.49 U	2.4 U
ug/m3	TO15	cis-1,2-Dichloroethene	0.2 U	0.79 U	4 U	2 U	8 U	0.4 U	2 U
ug/m3		cis-1,3-Dichloropropene	0.23 U	0.91 U	4.5 U	2.3 U	9.2 U	0.45 U	2.3 U
ug/m3		Cyclohexane	0.17 J	0.82 J	0.83 U	1.7 J	39	0.35 J	1.7 J
ug/m3		Dibromochloromethane	0.43 U	1.7 U	8.5 U	4.3 U	17 U	0.85 U	4.3 U
ug/m3	TO15	Dichlorodifluoromethane	2.9	3.1 J	10 J	0.59 U	2.4 U	3.1 J	0.59 U
ug/m3	TO15	Ethylbenzene	1.5	11	31	48	46	4.2	32
ug/m3	TO15	m,p-Xylene	5	40	110	170	160	15	110
ug/m3	TO15	Methyl tert-butyl ether	0.047 U	0.19 U	0.94 U	0.47 U	1.9 U	0.094 U	0.47 U

## TABLE 2 DATA USABILITY SUMMARY REPORT JANUARY 2011 INDOOR AIR AND SUB-SLAB VAPOR SAMPLING (μg/m3) FORMER HONEYWELL SITE

#### HOOSICK FALLS, NEW YORK

	·	Field Sample ID Location Sample Date	LS-AA-01-2 AA-01-2 1/26/2011	LS-IA-01-2 IA-01-2 1/26/2011	LS-IA-02-2 IA-02-2 1/26/2011	LS-IA-03-2 IA-03-2 1/26/2011	LS-IA-04-2 IA-04-2 1/26/2011	LS-IA-06-2 IA-06-2 1/26/2011	LS-IA-07-2 IA-07-2 1/26/2011
Units	Method	Parameter Name	1, 20, 2011	1,20,2011	1, 20, 2011	<i>a, ao, ao</i>	_, _, ,	<i>-, -, -, -, -, -, -, -, -, -, -, -, -, -</i>	_,,
ug/m3	TO15	Methylene Chloride	0.46 J	0.42 U	2.1 U	1 U	4.2 U	0.71 J	1 U
ug/m3		n-Heptane	0.31 J	4	2.2 U	2 J	18 J	0.7 J	1.9 J
ug/m3		n-Hexane	0.64 J	6.5	20	48	. 16 J	2.5	19
ug/m3		Tetrachloroethene	7.7	59	2200	5.5 J	4.7 U	22	530
ug/m3		Toluene	35	290	1300	750	5000	100	780
ug/m3		trans-1,2-Dichloroethene	0.2 U	0.79 U	4 U	2 U	8 U	0.4 U	2 U
ug/m3		trans-1,3-Dichloropropene	0.29 U	1.2 U	5.8 U	2.9 U	12 U	0.58 U	2.9 U
ug/m3		Trichloroethene	0.075 U	2.8 J	45	0.75 U	3 U	0.57 J	7.7 J
ug/m3	TO15	Trichlorofluoromethane	1.3	1.5 J	5.6 U	2.8 U	11 U	1.4 J	2.8 U
ug/m3		Vinyl chloride	0.064 U	0.26 U	1.3 U	0.64 U	2.6 U	0.13 U	0.64 U
ug/m3		Xylene (total)	6.1	49	130	200	200	18	130
ug/m3		Xylene, o-	1.1	8.7	23	34	37	3.4	23

## TABLE 2 DATA USABILITY SUMMARY REPORT JANUARY 2011 INDOOR AIR AND SUB-SLAB VAPOR SAMPLING (µg/m3) FORMER HONEYWELL SITE HOOSICK FALLS, NEW YORK

		Field Sample ID	LS-SS-01-2	LS-SS-01-2-D	LS-SS-02-2	LS-SS-04-2	LS-SS-05-2	LS-SS-06-2	LS-SS-07-2
		Location	SS-01-2	SS-01-2	SS-02-2	SS-04-2	SS-05-2	SS-06-2	SS-07-2
		Sample Date	1/26/2011	1/26/2011	1/26/2011	1/26/2011	1/26/2011	1/26/2011	1/26/2011
Units	Method	Parameter Name							
ug/m3	TO15.	1,1,1-Trichloroethane	9	8.7	0.27 U	0.27 U	12	0.59 J	1.4 J
ug/m3	TO15	1,1,2,2-Tetrachloroethane	2.7 U	2.7 U	0.34 U	0.34 U	0.34 U	0.34 U	1.5 U
ug/m3	TO15	1,1,2-Trichloroethane	2.2 U	2.2 U	0.27 U	0.27 U	0.27 U	0.27 U	1.2 U
ug/m3	TO15	1,1-Dichloroethane	0.42 U	0.42 U	0.053 U	0.053 U	0.053 U	0.053 U	0.22 U
ug/m3	TO15	1,1-Dichloroethene	0.48 U	0.48 U	0.059 U	0.059 U	0.059 U	0.059 U	0.25 U
ug/m3	TO15	1,2-Dibromoethane	0.74 U	0.74 U	0.092 U	0.092 U	0.092 U	0.092 U	0.39 U
ug/m3	TO15	1,2-Dichloroethane	0.49 U	0.49 U	0.061 U	0.061 U	0.061 U	0.061 U	0.26 U
ug/m3	TO15	1,2-Dichloroethene, Total	22	21	0.51 J	0.4 U	0.4 U	0.4 U	110
ug/m3	TO15	1,2-Dichloropropane	0.59 U	0.59 U	0.074 U	0.074 U	0.074 U	0.074 U	0.31 U
ug/m3	TO15	1,2-Dichlorotetrafluoroethane	0.67 U	0.67 U	0.084 U	0.084 U	0.084 U	0.084 U	0.36 U
ug/m3	TO15	1,3,5-Trimethylbenzene	2.5 U	2.5 U	0.31 U	3.6	2.2	1.8	1.3 U
ug/m3	TO15	1,3-Butadiene	0.48 U	0.48 U	0.06 U	0.06 U	0.06 U	0.06 U	0.25 U
ug/m3	TO15	2,2,4-Trimethylpentane	0.49 U	0.49 U	0.28 J	0.061 U	0.061 U	0.061 U	0.26 U
ug/m3	TO15	3-Chloropropene	0.73 U	0.73 U	0.091 U	0.091 U	0.091 U	0.091 U	0.39 U
ug/m3	TO15	4-Ethyltoluene	2.5 U	2.5 U	0.31 U	1.2	2.3	0.49 J	1.3 U
ug/m3	TO15	Benzene	1.3 U	1.3 U	1.3	0.52 J	1.1	0.54 J	0.68 U
ug/m3	TO15	Bromodichloromethane	11	.9.3 J	0.34 U	0.34 U	0.34 U	0.34 U	1.4 U
ug/m3	TO15	Bromoethene(Vinyl Bromide)	1.7 U	1.7 U	0.22 U	0.22 U	0.22 U	0.22 U	0.93 U
ug/m3	TO15	Bromoform	4.1 U	4.1 U	0.52 U	0.52 U	0.52 U	0.52 U	2.2 U
ug/m3	TO15	Bromomethane	0.43 U	0.43 U	0.054 U	0.054 U	0.054 U	0.054 U	0.23 U
ug/m3	TO15	Carbon tetrachloride	2.5 U	2.5 U	0.49 J	0.44 J	0.38 J	0.33 J	1.3 U
ug/m3	TO15	Chloroethane	2.1 U	2.1 U	0.26 U	0.26 U	0.26 U	0.26 U	1.1 U
ug/m3	TO15	Chloroform	26	24	0.24 U	0.24 U	0.24 U	0.24 U	1 U
ug/m3	TO15	cis-1,2-Dichloroethene	20	19	0.51 J	0.2 U	0.2 U	0.2 U	110
ug/m3	TO15	cis-1,3-Dichloropropene	1.8 U	1.8 U	0.23 U	0.23 U	0.23 U	0.23 U	0.97 U
ug/m3	TO15	Cyclohexane	0.33 U	0.33 U	0.31 J	0.21 J	0.3 J	0.35 J	0.18 U
ug/m3	TO15	Dibromochloromethane	3.4 U	3.4 U	0.43 U	0.43 U	0.43 U	0.43 U	1.8 U
ug/m3		Dichlorodifluoromethane	0.47 U	0.47 U	3	3.1	2.9	2.9	3.1 J
ug/m3	TO15	Ethylbenzene	0.49 U	0.49 U	0.71 J	0.59 J	3.4	1.9	0.26 U
ug/m3	TO15	m,p-Xylene	0.8 U	0.8 U	2.2	1.9 J	3.8	9.9	0.43 U
ug/m3	TO15	Methyl tert-butyl ether	0.37 U	0.37 U	0.047 U	0.047 U	0.047 U	0.047 U	0.2 U

3 of 4

# HONEPAHOOSICK-0000424

#### TABLE 2

#### **DATA USABILITY SUMMARY REPORT**

#### JANUARY 2011 INDOOR AIR AND SUB-SLAB VAPOR SAMPLING (µg/m3)

#### FORMER HONEYWELL SITE HOOSICK FALLS, NEW YORK

		Field Sample ID Location Sample Date	LS-SS-01-2 SS-01-2 1/26/2011	LS-SS-01-2-D SS-01-2 1/26/2011	LS-SS-02-2 SS-02-2 1/26/2011	LS-SS-04-2 SS-04-2 1/26/2011	LS-SS-05-2 SS-05-2 1/26/2011	LS-SS-06-2 SS-06-2 1/26/2011	LS-SS-07-2 SS-07-2 1/26/2011
Units	Method	Parameter Name	*						
ug/m3	TO15	Methylene Chloride	0.83 U	14 U	1.7 U	1.7 U	1.7 U	1.7 U	0.44 U
ug/m3	TO15	n-Heptane	0.89 U	0.89 U	0.47 J	0.7 J	1.4	1.3	0.47 U
ug/m3	TO15	n-Hexane	0.65 U	0.65 U	0.57 J	0.56 J	0.97	0.49 J	0.35 U
ug/m3	TO15	Tetrachloroethene	14	12	7.5	2.6	160	13	. 17
ug/m3		Toluene	5.2 J	4.2 J	14	9.2	14	13	3.8
ug/m3		trans-1,2-Dichloroethene	1.7 J	1.6 J	0.2 U	0.2 U	0.2 U	0.2 U	0.84 U
ug/m3	TO15	trans-1,3-Dichloropropene	2.3 U	2.3 U	0.29 U	0.29 U	0.29 ป	0.29 U	1.2 U
ug/m3	TO15	Trichloroethene	1100	980	4.5	0.75 J	40	2.4	560
ug/m3	TO15	Trichlorofluoromethane	2.2 U	2.2 U	1.5	1.5	1.5	1.5	1.6 J
ug/m3		Vinyl chloride	0.51 U	0.51 U	0.064 U	0.064 U	0.064 U	0.064 U	0.27 U
ug/m3	TO15	Xylene (total)	5.2 U	5.2 U	2.8	3	6	12	2.8 U
ug/m3	TO15	Xylene, o-	1.7 U	1.7 U	0.6 J	1.1	2.2	2.4	0.92 U

# HONEPAHOOSICK-0000425

#### TABLE 3

## DATA USABILITY SUMMARY REPORT JANUARY 2011 INDOOR AIR AND SUB-SLAB SAMPLING FORMER HONEYWELL SITE HOOSICK FALLS, NEW YORK

SDG	Lab ID	Method	Field Sample Id	Parameter Name	Lab Result	Lab Qualifier	Validated Result	Validation Qualifier	Reason Codes	Units
200-3615	200-3615-22	TO15	LS-SS-01-2-D	Methylene Chloride	1.5	J B	14	U	BL1	ug/m3
200-3615	200-3615-23	TO15	LS-SS-02-2	Methylene Chloride	0.54	JB	1.7	U	BL1	ug/m3
200-3615	200-3615-24	TO15	LS-SS-04-2	Methylene Chloride	0.63	JB.	1.7	U <sub>.</sub>	BL1	ug/m3
200-3615	200-3615-25	TO15	LS-SS-05-2	Methylene Chloride	0.69	JB	1.7	U	BL1	ug/m3
200-3615	200-3615-26	TO15	LS-SS-06-2	Methylene Chloride	0.80	JB	1.7	U	BL1	ug/m3

Mr. Christopher O'Neill, P.E. June 2011

Mr. Christopher O'Neill, P.E. MACTEC Project: 3410100802

### ATTACHMENT D JANUARY 2011 PHOTOGRAPHS



Photo 1: Liberty Street Indoor air sample at IA-01




Photo 2: Liberty Street IA-01sample




Photo 3: Liberty Street indoor air sample at IA-02 in Breakroom adjacent to Machine shop



Photo 4: Liberty Street IA-02 in Breakroom adjacent to Machine shop



Photo 5: Liberty Street indoor air sample IA-03 in the supervisor's office



Photo 6: Liberty Street indoor air sample IA-04 in QA office



Photo 7: Liberty Street IA-04 and SS-04



Photo 8: Liberty Street indoor air sample IA-06 in Human Resource's office



Photo 9: Liberty Street samples SS-01 and SS-01-D in electrical room



Photo 10: Liberty Street sample SS-02 in the warehouse



Photo 11: Liberty Street sample SS-04 in QA office



Photo 12: Liberty Street sample SS-05 in office



Photo 13: Liberty Street sample SS-06 in human resource's office



Photo 14: Liberty Street sample location SS-07 completion



**Photo 15: Liberty Street Machine shop** 



Photo 16: Liberty Street Flammable Cabinets in Machine shop



Photo 17: Liberty Street Flammable cabinet 2 in Machine shop



Photo 18: Zep Lubrisil in Flammable Cabinet in Machine shop



Photo 19: Zep Lubrisil in Flammable Cabinet in Machine shop



Photo 20: Liberty Street Chemical Inventory in Machine shop



Photo 21: Liberty Street Chemical Inventory Near IA-06



Photo 22: Flammable cabinet near IA-07